

EXHIBIT G

WORK START DATE:

CONTRACTOR

WORK AUTHORIZATION FORM

1. USS MCFAUL (DDG-74)	2. SYSTEM SSGTG INTAKE #2	3. WAF NO. 0271
4. JCN	5. COMPANY/ SHOP / REP / PHONE AIT-MARINE / KELVIN BUIE / 757-335-1010	
7. JOB DESCRIPTION & LOCATION	6. TECHNICAL WORK DOCUMENT 251-30-002	
KTR REQUEST BLOW-IN DOOR TO BE TAGGED OUT IN THE OPEN POSITION IN-ORDER TO REMOVE AND INSTALL NEW GASKET IN COMPARTMENT 01-260-1-Q.		

PREPARATION FOR WORK

8. POST WORK TESTING IS AS SPECIFIED: <input type="checkbox"/> BELOW <input type="checkbox"/> IN THE TWD <input type="checkbox"/> NO TEST REQD <input checked="" type="checkbox"/> FORMAL TEST PROGRAM
9. RESTRICTIONS/PRECAUTIONS/REMARKS.
10. DIVISION/REPAIR ACTIVITY READY TO COMMENCE WORK. LPO/DIV OFF or RA <u>Kelvin Buie</u> DATE _____

AUTHORIZATION TO WORK

11. SAFETY OF SHIP (Submarine Only): <input type="checkbox"/> YES <input type="checkbox"/> NO RA SSO (if SPOD used) or QUALIFIED WATCH/DUTY OFFICER (if SOSMIL used) <u>N/A</u> DATE <u>N/A</u>
12. CONCURRENCES: <u>1/29/21</u> DATE _____ DATE _____ DATE _____
13. TAGOUT REQUIRED: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO SYSTEM/COMPONENT IS LINED UP FOR WORK, A TAG OUT IS HUNG, VERIFIED AND SIGNED BY THE REPAIR ACTIVITY (IF REQUIRED) AND SHIP. TAGOUT NO. <u>EM02[WAF-0271] SSGTG #2 INTAKE 27 JAN 21 (00)</u> WATCH/DUTY OFF <u>GC</u> DATE <u>27 Jan 21</u>
14. PLANT/SHIP CONDITIONS (E.G., DRAINED, DE-PRESSURIZED, DE-ENERGIZED, RESTRAINED) SET. DIVISION/RA IS AUTHORIZED TO START WORK. WATCH/DUTY OFF <u>GC</u> DATE <u>20 Jan 21</u> RA <u>ACB</u> DATE <u>1/29/21</u>

NOTIFICATION OF WORK COMPLETION

15. RESTRICTIONS/PRECAUTIONS/REMARKS	
16. WORK IS COMPLETE RA _____ DATE _____	17. TESTING IS COMPLETE WATCH/DUTY OFF or RA _____ DATE _____
18. WAF CLOSED OUT WATCH/DUTY OFF _____ DATE _____ WAF COR _____ DATE _____	

☐ CHECK IF CONTINUED ON ANOTHER SHEET

The WAF must match the work and it must be on the job site. SHEET 1

Reference: COMUSFLTFORCOMINST 4790.3 (JFMM) REV D

WORK START DATE:

CONTRACTOR WORK AUTHORIZATION FORM

1. USS MCFAUL (DDG-74)	2. SYSTEM SSGTG INTAKE #2	3. WAF NO. 0271
4. JCN	5. COMPANY/ SHOP / REP / PHONE AIT-MARINE / KELVIN BUIE / 757-335-1010	
7. JOB DESCRIPTION & LOCATION	6. TECHNICAL WORK DOCUMENT 251-30-002	
KTR REQUEST BLOW-IN DOOR TO BE TAGGED OUT IN THE OPEN POSITION IN-ORDER TO REMOVE AND INSTALL NEW GASKET IN COMPARTMENT 01-260-1-Q.		

PREPARATION FOR WORK

8. POST WORK TESTING IS AS SPECIFIED: <input type="checkbox"/> BELOW <input type="checkbox"/> IN THE TWD <input type="checkbox"/> NO TEST REQD <input checked="" type="checkbox"/> FORMAL TEST PROGRAM
9. RESTRICTIONS/PRECAUTIONS/REMARKS.
10. DIVISION/REPAIR ACTIVITY READY TO COMMENCE WORK. LPO/DIV OFF or RA <u>Kelvin Buie</u> DATE _____

AUTHORIZATION TO WORK

11. SAFETY OF SHIP (Submarine Only): <input type="checkbox"/> YES <input type="checkbox"/> NO RA SSO (if SPOD used) or QUALIFIED WATCH/DUTY OFFICER (if SOSMIL used) <u>N/A</u> DATE <u>N/A</u>
12. CONCURRENCES: <u>[Signature]</u> DATE <u>1/29/21</u> _____ DATE _____ DATE _____
13. TAGOUT REQUIRED: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO SYSTEM/COMPONENT IS LINED UP FOR WORK, A TAG OUT IS HUNG, VERIFIED AND SIGNED BY THE REPAIR ACTIVITY (IF REQUIRED) AND SHIP. TAGOUT NO. <u>EM02[WAF-0271] SSGTG #2 INTAKE 27 JAN 21 (00)</u> WATCH/DUTY OFF <u>[Signature]</u> DATE <u>21 JAN 21</u>
14. PLANT/SHIP CONDITIONS (E.G., DRAINED, DE-PRESSURIZED, DE-ENERGIZED, RESTRAINED) SET. DIVISION/RA IS AUTHORIZED TO START WORK. WATCH/DUTY OFF <u>[Signature]</u> DATE <u>20 JAN 21</u> RA <u>[Signature]</u> DATE <u>1/29/21</u>

NOTIFICATION OF WORK COMPLETION

15. RESTRICTIONS/PRECAUTIONS/REMARKS	
16. WORK IS COMPLETE RA _____ DATE _____	17. TESTING IS COMPLETE WATCH/DUTY OFF or RA _____ DATE _____
18. WAF CLOSED OUT WATCH/DUTY OFF _____ DATE _____ WAF COR _____ DATE _____	

☐ CHECK IF CONTINUED ON ANOTHER SHEET

The WAF must match the work and it must be on the job site.

SHEET 1

Reference: COMUSFLTFORCOMINST 4790.3 (JFMM) REV D

2 GTG INTAKES

REMOVE AND INSTALL NEW GASKET IN COMPARTMENT 01-260-1-Q.

REASON FOR TAG-OUT

F-0271

PERSONNEL/EQUIPMENT HAZARDS INVOLVED

FOD

WORK NECESSARY TO CLEAR TAG(S) (INCLUDING TESTS)

REMOVE AND INSTALL NEW GASKET IN COMPARTMENT 01-260-1-Q AND RETURN EQUIPMENT TO LAY UP CONDITION.

APPLICABLE DOCUMENTATION (I.E., JOB ORDER, RIP-OUT, S/P, ETC.)	DATE/TIME ISSUED OR ADDED	PETTY OFFICER IN-CHARGE	ACCURACY/ADEQUACY CHECK	REPAIR ACTIVITY REP. (WORK COMPLETE) (WHEN APPROPRIATE)
		CROSS CHECK (WHEN REQ.)	REP. ACT. REP. (WHEN APP.)	
		SECOND PERSON	AUTH. OFFICER (ISSUED)	WCS OR POIC (WORK COMPLE)
		CROSS CHECK (WHEN REQ.)	AUTH. OFFICER (HUNG)	AUTH. OFFICER (TAGS REMOVL
SEE REASON BLOCK	27-JAN-21 1342	GSM3 CRESPO, CHRISTOPHER 27-JAN-21		
			KELVIN BUIE 27-JAN-21 1327	
		GSM3 Roberts, Austin 27-JAN-21 1035	GSM1 Praetam, Anita 27-JAN-21 1342	

Tag	Status	RA Required (# Line Items)	RA Witness (Initial)	COMPONENT	LOCATION	POSITION
9680		Yes (14)	V65	GSA-V-3	4-254-0-E	SHUT
9673		Yes (16)	V63	AHP-V-146	4-254-0-E	SHUT
9681		Yes (10)	V6B	GBA2-V-4	4-254-0-E	SHUT
9908	*	Yes (1)	V6B	NR 2 GTG BLOW'IN CONTROL	4-254-0-E	OPEN
9672		Yes (14)	V6	GFS2-V-3	4-254-0-E	SHUT

AIT

* - Tag is to be hung on this line item
+ - Tag is issued on a previous line item
and is not yet reported hung